

| WTR-2000-UKx | | | |
|--------------|--------------------|--------------|------------|
| Seagate | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 8T | ST8000VX0002 | all | 2017.05.03 |
| | ST8000NM0055 | all | 2017.05.03 |
| 6T | ST6000VX001 | all | 2017.05.03 |
| | ST6000NM0115 | all | 2017.05.03 |
| 4T | ST4000VX000 | all | 2017.05.03 |
| 3T | ST3000VX006 | all | 2017.05.03 |
| 1T | ST1000VX001 | all | 2017.05.03 |
| WD | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 8T | WD80PURZ-85YNPY0 | all | 2017.05.03 |
| 6T | WD60PURX | all | 2017.05.03 |
| | WD6002FRYZ-01WD5B0 | all | 2017.05.03 |
| 4T | WD40PURX | all | 2017.05.03 |
| 3T | WD30PURX | all | 2017.05.03 |
| 2T | WD2004FBYZ-01YCBB0 | all | 2017.05.03 |
| | WD20EURS-73TLHY0 | all | 2017.05.03 |

WTR-2000-HDT, WTR-2000-FHDT, WTR-2000-UFx

Seagate

| Capacity | HDD Model | DVR Firmware | Update |
|-------------|-------------|--------------|-----------|
| 4T | ST4000VM000 | all | 2013.6.26 |
| | ST4000VX000 | all | 2014.6.23 |
| | ST4000VX002 | all | 2015.6.19 |
| | ST3000VX006 | all | 2016.4.18 |
| 3T | ST3000VX005 | all | 2015.6.19 |
| | ST3000VX004 | all | 2015.6.19 |
| | ST3000VM002 | all | 2013.6.26 |
| | ST3000VX000 | all | |
| | | | |
| 2T | ST2000VX005 | all | 2015.6.19 |
| | ST2000VX004 | all | 2015.6.19 |
| | ST2000VX003 | all | 2016.4.18 |
| | ST2000VX000 | all | |
| | ST2000VM002 | all | |
| | ST2000VM003 | all | 2014.6.23 |
| | | | |
| 1T | ST1000VX003 | all | 2015.6.19 |
| | ST1000VX002 | all | 2015.6.19 |
| | ST1000VM002 | all | |
| | ST1000VX001 | all | 2016.4.18 |
| | | | |
| | | | |
| 500G | | | |
| | ST3500410SV | all | |

WD

| Capacity | HDD Model | DVR Firmware | Update |
|-----------|--------------------|--------------|-----------|
| 6T | WD60PURX-78T0ZY1 | all | 2017.7.5 |
| | WD60PURX-64T0ZY1 | all | 2017.7.5 |
| | WD6002FRYZ-01WD5B0 | all | 2016.8.9 |
| 4T | WD4002FYYZ-01B7CB0 | all | 2016.8.9 |
| | WD40EURX | all | 2014.1.21 |
| | WD40PURX | all | 2014.4.7 |
| 3T | WD30EURX | all | 2014.1.21 |
| | WD30EURS | all | |
| | WD30PURX | all | 2014.4.7 |
| 2T | WD20EVDS | all | |
| | WD20EURX | all | 2014.1.21 |
| | WD20PURX | all | 2014.4.7 |
| 1T | WD10PURX | all | 2014.4.7 |

Seznam kompatibilních HDD

9.3.2018

| | | | |
|-----------------|------------------|---------------------|---------------|
| 500G | WD05PURZ-85U8XY0 | all | 2015.6.30 |
| TOSHIBA | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 5T | MD04ABA500V | all | 2014.12.30 |
| | MD04ABA400V | all | 2014.12.30 |
| 4T | MD03ACA400V | all | 2014.8.18 |
| | MD03ACA300V | all | 2014.8.18 |
| 3T | DT01ABA300V | all | 2013.8.23 |
| | MD03ACA200V | all | 2014.8.18 |
| 2T | DT01ABA200V | all | 2013.8.23 |
| | DT01ABA100V | all | 2013.8.23 |

| WNR-7600-NISE (Px) | | | |
|---------------------------|------------------|---------------------|---------------|
| Seagate | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 4T | ST4000VX002 | all | 2015.6.19 |
| | ST4000VM000 | all | 2014.1.21 |
| 3T | ST3000VX006 | all | 2016.4.18 |
| | ST3000VX005 | all | 2015.6.19 |
| | ST3000VX004 | all | 2015.6.19 |
| | ST3000VX000-9YW1 | all | |
| 2T | ST2000VX005 | all | 2015.6.19 |
| | ST2000VX004 | all | 2015.6.19 |
| | ST2000VX003 | all | 2016.4.18 |
| | ST2000VX000-9YW1 | all | |
| | ST2000VX002-1AH1 | all | |
| | ST2000VM003-1CT1 | all | |
| 1T | ST1000VX003 | all | 2015.6.19 |
| | ST1000VX002 | all | 2015.6.19 |
| | ST1000VX001 | all | 2016.4.18 |
| | ST1000VM002-9ZL1 | all | |
| | ST31000322CS | all | |
| | ST1000VX000-9YW1 | all | |
| | ST31000526SV | all | |
| 500G | ST3500410SV | all | |
| | ST3500411SV | all | |
| 250G | ST3250312CS | all | |
| | ST3250310SV | all | |
| | ST3250820SV | all | |
| WD | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 4T | WD40PURX-64GVNY0 | all | |
| 3T | WD30PURZ-85GU6Y0 | all | |
| 2T | WD20PURZ-85GU6Y0 | all | |
| | WD20EURS-63S | all | |
| 1T | WD10PURX-64D85Y0 | all | |
| | WDC WD10EVDS-63U | all | |
| 500G | WD5000AVVS-6 | all | |
| | WD05PURZ-85U8XY0 | all | 2015.6.30 |
| Hitachi | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 2T | Hitachi HUA72202 | all | |
| Samsung | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 2T | SAMSUNG HD204UI | all | |
| TOSHIBA | | | |

| Capacity | HDD Model | DVR Firmware | Update |
|-----------------|------------------|---------------------|---------------|
| 5T | MD04ABA500V | all | 2014.12.30 |
| 4T | MD04ABA400V | all | 2014.12.30 |
| | MD03ACA400V | all | 2014.8.18 |
| 3T | MD03ACA300V | all | 2014.8.18 |
| 3T | DT01ABA300V | all | 2013.8.23 |
| 2T | MD03ACA200V | all | 2014.8.18 |
| 2T | DT01ABA200V | all | 2013.8.23 |
| 1T | DT01ABA100V | all | 2013.8.23 |
| Hitachi | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 4T | HUS724040ALA640 | V3.0.1 Build 140310 | 2014.9.30 |

| WNR-2000-Ex (Px), WNR-4000-E4 (Px) | | | |
|---|------------------|----------------------|---------------|
| Seagate | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 6T | ST6000VX0001 | V3.4.6build 160405 | 2016.8.12 |
| 4T | ST4000VX007 | V3.4.6build 160405 | 2016.10.10 |
| | ST4000VX002 | V3.0.6build 140526 | 2015.6.19 |
| | ST4000VM000 | V3.0.5 Build 140508 | 2014.6.23 |
| | ST4000VX000 | V3.0.5 Build 140508 | 2014.6.23 |
| 3T | ST3000VX010 | V3.0.6build 140526 | 2016.10.10 |
| | ST3000VX006 | V3.0.6build 140526 | 2016.4.18 |
| | ST3000VX005 | V3.0.6build 140526 | 2015.6.19 |
| | ST3000VX004 | V3.0.6build 140526 | 2015.6.19 |
| | ST3000VX000 | V3.0.5 Build 140508 | 2014.8.11 |
| | ST3000VM002 | V3.0.5 Build 140508 | 2014.6.23 |
| 2T | ST2000VX008 | V3.0.6build 140526 | 2016.10.10 |
| | ST2000VX005 | V3.0.6build 140526 | 2015.6.19 |
| | ST2000VX004 | V3.0.6build 140526 | 2015.6.19 |
| | ST2000VX003 | V3.0.6build 140526 | 2016.4.18 |
| | ST2000VM002 | V3.0.5 Build 140508 | 2014.6.23 |
| | ST2000VX000 | V3.0.5 Build 140508 | 2014.6.23 |
| 1T | ST1000VX005 | V3.0.6build 140526 | 2016.10.10 |
| | ST1000VX003 | V3.0.6build 140526 | 2015.6.19 |
| | ST1000VX002 | V3.0.6build 140526 | 2015.6.19 |
| | ST1000VX000 | V3.0.5 Build 140508 | 2014.6.23 |
| | ST1000VM002 | V3.0.5 Build 140508 | 2014.6.23 |
| | ST1000VX001 | V3.0.6build 140526 | 2016.4.18 |
| WD | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 6T | WD60PURX-78T0ZY1 | V3.4.95 build 170626 | 2017.7.14 |
| 6T | WD60PURX-64T0ZY1 | V3.4.95 build 170626 | 2017.7.14 |
| 6T | WD60PURX-78LZMY0 | V3.4.6build 160405 | 2016.8.12 |
| 6T | WD60PURX-64LZMY0 | V3.4.6build 160405 | 2016.8.12 |
| 4T | WD40PURX | V3.0.5 Build 140508 | 2014.6.23 |
| 3T | WD30PURX | V3.0.5 Build 140508 | 2014.6.23 |
| | WD30EURS | V3.0.5 Build 140508 | 2014.6.23 |
| 2T | WD20PURX | V3.0.5 Build 140508 | 2014.6.23 |
| | WD20EURS | V3.0.5 Build 140508 | 2014.6.23 |
| 1T | WD10PURX | V3.0.5 Build 140508 | 2014.6.23 |
| | WD10EURX | V3.0.5 Build 140508 | 2014.6.23 |
| 500G | WD05PURZ-85U8XY0 | V3.0.5 Build 140508 | 2015.6.30 |
| TOSHIBA | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 5T | MD04ABA500V | all | 2014.12.30 |
| 4T | MD04ABA400V | all | 2014.12.30 |
| | MD03ACA400V | all | 2014.8.18 |
| 3T | MD03ACA300V | all | 2014.8.18 |

Seznam kompatibilních HDD

9.3.2018

| | | | |
|-----------------|------------------|---------------------|---------------|
| 2T | MD03ACA200V | all | 2014.8.18 |
| Hitachi | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 4T | HUS724040ALA640 | V3.0.1 Build 140310 | 2014.9.30 |

| WNR-2000-I2 (Px), WNR-4000-I4 (Px), WNR-4900-I8/16 | | | | | |
|---|-----------------|--------------------|-------------------------|-----------|---|
| Note: the hard disks used for RAID must be enterprise-class or support RV sensors. | | | | | |
| Y: support RV N: not support RV | | | | | |
| WD | | | | | |
| Type | Capacity | Model | Firmware version | RV | Notes |
| Enterprise | 10T | WD101KRYZ-01JPDB0 | V4.1.0 Build170915 | Y | 2018.02.28 only for I8/I16 |
| Surveillance | 10T | WD100PUAX-64TRWY0 | V4.1.0 Build170915 | Y | 2018.02.28 only for I8/I16 |
| Surveillance | 10T | WD100PUAX-78TRWY0 | V4.1.0 Build170915 | Y | 2018.02.28 only for I8/I16 |
| Surveillance | 8T | WD80PUZX-64NEAY0 | V3.4.2 Build160205 | Y | 2018.02.28 |
| Surveillance | 6T | WD60PURX-78T0ZY1 | V3.4.95 build 170626 | Y | 2017.7.14 |
| Surveillance | 6T | WD60PURX-64T0ZY1 | V3.4.95 build 170626 | Y | 2017.7.14 |
| Enterprise | 6T | WD6002FRYZ-01WD5B0 | V3.4.2 Build160205 | Y | Verified only on WNR-49xx (Raid is enabled) |
| Surveillance | 4T | WD40PURX-64NZ6Y0 | V3.4.2 Build160205 | Y | 2018.02.28 |
| Surveillance | 4T | WD40PURX-78NZ6Y0 | V3.4.2 Build160205 | Y | 2018.02.28 |
| Enterprise | 4T | WD4002FYYZ-01B7CB0 | V3.4.2 Build160205 | Y | Verified only on WNR-49xx (Raid is enabled) |
| Enterprise | 4T | WD4000FYYZ-01UL1B0 | V3.3.5 Build150717 | Y | Verified only on WNR-49xx (Raid is enabled) |
| Surveillance | 3T | WD30PURX | V3.3.7 Build151030 | N | |
| Surveillance | 2T | WD20PURX | V3.3.7 Build151030 | N | |
| Enterprise | 2T | WD2000FYYZ-01UL1B1 | V3.3.5 Build150717 | Y | Verified only on WNR-49xx (Raid is enabled) |
| Surveillance | 2T | WD20EURS-63S48Y0 | V3.3.5 Build150717 | N | |
| Enterprise | 2T | WD2004FBYZ-01YCBBO | V3.3.5 Build150717 | Y | Verified only on WNR-49xx (Raid is enabled) |
| Surveillance | 1.5T | WD15EURS-63S48Y0 | V3.3.5 Build150717 | N | |
| Surveillance | 1T | WD10EURX-63FH1Y0 | V3.3.5 Build150717 | N | |
| Surveillance | 1T | WD10EURX-63FH1Y0 | V3.3.5 Build150717 | N | |
| Seagate | | | | | |
| Type | Capacity | Model | Firmware version | RV | Update |
| Enterprise | 10T | ST10000NM0016 | V4.1.0 Build170915 | Y | 2018.02.28 only for I16 |
| Surveillance | 10T | ST10000VX0004 | V4.1.0 Build170915 | Y | 2018.02.28 only for I8/I16 |
| Surveillance | 8T | ST8000VX0002 | V3.3.5 Build150717 | Y | 2018.02.28 only for 49-I8/I16 |
| Enterprise | 8T | ST8000NM0055 | V3.3.5 Build150717 | Y | 2018.02.28 only for 49-I8/I16 |

Seznam kompatibilních HDD

9.3.2018

| | | | | | |
|---------------------|-----------------|---------------------|------------------------------------|-----------|---|
| Surveillance | 8T | ST8000VX0022 | V3.3.5 Build150717 | Y | 2018.02.28 only for 49-I8/I16 |
| Enterprise | 6TB | ST6000NM0115 | V3.4.2 Build160205 | Y | 2018.02.28 only for 49-I8/I16 |
| Surveillance | 6TB | ST6000VX0023 | V3.4.2 build 160205 | Y | |
| Surveillance | 6TB | ST6000VX0003 | all | Y | |
| Surveillance | 6T | ST6000VX0011 | | Y | |
| Surveillance | 6T | ST6000VX0001 | | Y | |
| Surveillance | 4TB | ST4000VX007 | V3.4.2 build 160205 | Y | |
| Enterprise | 4T | ST4000NM0033-9ZM170 | V3.3.5 Build150717 | Y | Verified only on WNR-49xx (Raid is enabled) |
| Surveillance | 4T | ST4000VX000 | V3.3.7 Build151030 | Y | |
| Surveillance | 3T | ST3000VX010 | V3.3.7 Build 151102 | N | 2018.02.28 |
| Surveillance | 3T | ST3000VX006 | V3.3.7 Build151030 | N | 2018.02.28 |
| Enterprise | 3T | ST3000NM0005 | V3.4.2 Build160205 | Y | 2018.02.28 |
| Enterprise | 3T | ST3000NM0055 | V3.4.2 Build160205 | Y | 2017.3.14 |
| Surveillance | 3T | ST3000VX000-1CU166 | V3.3.5 Build150717 | N | |
| Surveillance | 3T | ST3000VX006 | V3.3.7 Build151030 | N | |
| Surveillance | 2T | ST2000VX000-9YW164 | V3.3.5 Build150717 | N | |
| Surveillance | 2T | ST2000VX002-1AH166 | V3.3.5 Build150717 | N | |
| Surveillance | 2T | ST2000VM003-1CT164 | V3.3.5 Build150717 | N | |
| Surveillance | 2T | ST2000VX003 | V3.3.7 Build151030 | N | |
| Enterprise | 2T | ST2000NM0055 | V3.4.2 Build160205 | Y | 2017.3.14 |
| Surveillance | 1T | ST1000VX005 | V3.3.7 Build151102 | N | 2018.02.28 |
| Surveillance | 1T | ST1000VX000-9YW162 | V3.3.5 Build150717 | N | |
| Surveillance | 1T | ST1000VM002-1CT162 | V3.3.5 Build150717 | N | |
| Surveillance | 1T | ST1000VX001 | V3.3.7 Build151030 | N | |
| Enterprise | 1T | ST1000NM0055 | V3.4.2 Build160205 | Y | 2017.3.14 |
| Surveillance | 750G | ST3750330SV | V3.3.5 Build150717 | N | |
| Surveillance | 500G | ST3500312CS | V3.3.5 Build150717 | N | |
| Surveillance | 500G | ST3500410SV | V3.3.5 Build150717 | N | |
| Surveillance | 500G | ST3500411SV | V3.3.5 Build150717 | N | |
| TOSHIBA | | | | | |
| Type | Capacity | Model | Firmware version | RV | Update |
| Enterprise | 6T | MG04ACA600E | Supported on WNR-49xx-I8/I16(raid) | Y | 2016.09.26 |

| WNR-2000-Kx (Px), WNR-4000-K4 (Px) | | | | |
|---|-----------------|--------------------|-------------------------|---------------|
| WD | | | | |
| Type | Capacity | Model | Firmware version | Notes |
| Surveillance | 6T | WD60PURX-78T0ZY1 | V3.4.95 build 170626 | 2017.7.14 |
| Surveillance | 6T | WD60PURX-64T0ZY1 | V3.4.95 build 170626 | 2017.7.14 |
| Surveillance | 3T | WD30PURX | V3.3.7 Build151030 | |
| Surveillance | 2T | WD20PURX | V3.3.7 Build151030 | |
| Surveillance | 2T | WD20EURS-63S48Y0 | V3.3.5 Build150717 | |
| Surveillance | 1.5T | WD15EURS-63S48Y0 | V3.3.5 Build150717 | |
| Surveillance | 1T | WD10EURX-63FH1Y0 | V3.3.5 Build150717 | |
| Surveillance | 1T | WD10EURX-63FH1Y0 | V3.3.5 Build150717 | |
| Seagate | | | | |
| Type | Capacity | Model | Firmware version | Update |
| Surveillance | 6TB | ST6000VX0023 | V3.4.2 build 160205 | |
| Surveillance | 6TB | ST6000VX0003 | all | |
| Surveillance | 6T | ST6000VX0011 | | |
| Surveillance | 6T | ST6000VX0001 | | |
| Surveillance | 4TB | ST4000VX007 | V3.4.2 build 160205 | |
| Surveillance | 4T | ST4000VX000 | V3.3.7 Build151030 | |
| Surveillance | 3T | ST3000VX010 | V3.3.7 Build 151102 | 2018.02.28 |
| Surveillance | 3T | ST3000VX006 | V3.3.7 Build151030 | 2018.02.28 |
| Enterprise | 3T | ST3000NM0005 | V3.4.2 Build160205 | 2018.02.28 |
| Enterprise | 3T | ST3000NM0055 | V3.4.2 Build160205 | 2017.3.14 |
| Surveillance | 3T | ST3000VX000-1CU166 | V3.3.5 Build150717 | |
| Surveillance | 3T | ST3000VX006 | V3.3.7 Build151030 | |
| Surveillance | 2T | ST2000VX000-9YW164 | V3.3.5 Build150717 | |
| Surveillance | 2T | ST2000VX002-1AH166 | V3.3.5 Build150717 | |
| Surveillance | 2T | ST2000VM003-1CT164 | V3.3.5 Build150717 | |
| Surveillance | 2T | ST2000VX003 | V3.3.7 Build151030 | |
| Enterprise | 2T | ST2000NM0055 | V3.4.2 Build160205 | 2017.3.14 |
| Surveillance | 1T | ST1000VX005 | V3.3.7 Build151102 | 2018.02.28 |
| Surveillance | 1T | ST1000VX000-9YW162 | V3.3.5 Build150717 | |
| Surveillance | 1T | ST1000VM002-1CT162 | V3.3.5 Build150717 | |
| Surveillance | 1T | ST1000VX001 | V3.3.7 Build151030 | |
| Enterprise | 1T | ST1000NM0055 | V3.4.2 Build160205 | 2017.3.14 |
| Surveillance | 750G | ST3750330SV | V3.3.5 Build150717 | |
| Surveillance | 500G | ST3500312CS | V3.3.5 Build150717 | |
| Surveillance | 500G | ST3500410SV | V3.3.5 Build150717 | |
| Surveillance | 500G | ST3500411SV | V3.3.5 Build150717 | |

| WNR-7700-NIST, WNR-8600-NIST | | | | |
|-------------------------------------|------------------------------|---------------------------------|-------------------------|---------------|
| Seagate | | | | |
| Capacity | HDD Series | HDD Model | DVR Firmware | Update |
| 6T | | ST6000VX0023 | Netra (not enable raid) | 2016.10.10 |
| | | ST6000VX0003 | Netra (not enable raid) | 2016.09.26 |
| 4T | | ST4000VX007 | Netra (not enable raid) | 2016.10.10 |
| | Seagate Video 3.5 HDD 4000GB | ST4000VM000 | all | 2013.6.26 |
| | | ST4000VX002 | all | 2015.6.19 |
| | | ST4000VX000 | all | 2014.6.23 |
| 3T | | ST3000VX006 | all | 2016.4.18 |
| | | ST3000VX010 | Netra (not enable raid) | 2016.10.10 |
| | | ST3000VX005 | all | 2015.6.19 |
| | | ST3000VX004 | all | 2015.6.19 |
| | Seagate Video 3.5 HDD 3000GB | ST3000VM002 | all | 2013.6.26 |
| | | ST3000VM002 | all | 2014.6.23 |
| | Seagate SV35.7™ 3000GB | ST3000VX000 | all | 2013.1.18 |
| | Seagate SV35™ 3000GB | ST3000VX000 | all | 2012.3.8 |
| | ST3000NM0005 | V3.4.1build151225 | 2017.3.15 | |
| 2T | | ST2000VX008 | Netra (not enable raid) | 2016.10.10 |
| | | ST2000VX005 | all | 2015.6.19 |
| | | ST2000VX004 | all | 2015.6.19 |
| | | ST2000VX003 | all | 2016.4.18 |
| | Seagate SV35.7™ 2000GB | ST2000VX000 | all | 2013.1.18 |
| | Seagate SV35™ 2000GB | ST2000VX000 | all | 2012.3.8 |
| | Seagate Pipeline 2000GB | ST2000VM002 | all | |
| | | ST2000VM003 | all | 2014.6.23 |
| | Seagate SV35.5™ 2000GB | ST2000VX002(SATAIII) | all | |
| | | ST2000NM0055 | V3.4.1build151225 | 2017.3.15 |
| 1T | | ST1000VX005 | Netra (not enable raid) | 2016.10.10 |
| | | ST1000VX003 | all | 2015.6.19 |
| | | ST1000VX002 | all | 2015.6.19 |
| | | ST1000VX001 | all | 2016.4.18 |
| | Seagate SV35.7™ 1000GB | ST1000VX000 | all | 2013.1.18 |
| | Seagate SV35™ 1000GB | ST1000VX000 | all | 2012.3.8 |
| | Seagate Pipeline HD™ 1000GB | ST1000VM002 | all | |
| | | ST1000VM002 | all | 2014.6.23 |
| | Seagate SV35.5™ 1TB | ST31000526SV(SATAIII) | all | |
| | Seagate SV35.5 1000 Gbytes | ST31000525SV | all | |
| | Seagate SV35.3 1000 Gbytes | ST31000340SV, P/N:9DM158-901 | all | |

| | | | | |
|-----------------|---|---|---------------------|---------------|
| | Seagate Barracuda ES.2 1000 Gbytes | ST31000340NS | all | |
| | Seagate Pipeline HD2 1000 Gbytes | ST31000322CS | all | |
| | | ST1000NM0055 | V3.4.1build151225 | 2017.3.15 |
| 750G | Seagate SV35.2 750 Gbytes SATA (+5V +12V, 0.52A 0.72A) | ST3750640SV, P/N:9DC148-901, Firmware:3.ACE | all | |
| | Seagate SV35.3 750 Gbytes | ST3750330SV, P/N:9DM156-901 | all | |
| 500G | Seagate SV35.5™ 500G | ST3500411SV(SATAIII) | all | |
| | Seagate SV35.2 500 Gbytes (+5V +12V, 0.52A 0.72A) | ST3500630SV, P/N:9DC146-901, Firmware:3.ACE | all | |
| | Seagate SV35.3 500 Gbytes | ST3500320SV, P/N:9DM154-901 | all | |
| | Seagate PipelineHD 500 Gbytes | ST3500321CS | all | |
| | Seagate Pipeline HD2 500 GBYTES | ST3500312CS | all | |
| | Seagate SV35.5 500 Gbytes | ST3500410SV | all | |
| | Seagate SV35.1 500 Gbytes (+5V +12V, 0.46A 0.56A) | ST3500641SV, P/N:9CS148-501, Firmware:3.01 | all | |
| 320G | Seagate SV35.2 320 Gbytes (+5V +12V, 0.72A 0.52A) SATA | ST3320620SV, P/N:9DC14G-901, Firmware:3.ACE | all | |
| | Seagate SV35.4 320 Gbytes | ST3320410SV | all | |
| 250G | Seagate SV35.1 250G SATA | ST3250824SV | all | |
| | Seagate SV35.2 250 Gbytes (+5V +12V, 0.52A 0.72A) | ST3250820SV, P/N:9DC13E-901, Firmware:3.ACE | all | |
| | Seagate SV35.3 250G | ST3250310SV, P/N:9FD132-901, Firmware:3.ACC | all | |
| | Seagate SV35.5 250 Gbytes | ST3250311SV | all | |
| WD | | | | |
| Capacity | HDD Series | HDD Model | DVR Firmware | Update |
| 4T | WD40EURX WD AV | WD40EURX-64WRWY0 | all | 2014.1.21 |
| | WD40PURX WD AV | WD40PURX-64GVNY0 | all | 2014.4.7 |
| 3T | WD30EURX WD AV | WD30EURX-63T0FY0 | all | 2014.1.21 |
| | WD30EURX WD AV | WD30EURX-64HYZY0 | all | 2014.1.21 |
| | WD30EURX WD AV | WD30EURX-78T0FY0 | all | 2014.1.21 |
| | WD30EURS WD AV-GP | WD30EURS-63SPKY0 | all | 2012.11.6 |
| | WD30EURS WD AV-GP | WD30EURS-63R8UY0 | all | 2012.3.8 |
| | WD30PURX WD AV | WD30PURZ-85GU6Y0 | all | 2014.4.7 |
| | WD20EURX WD AV | WD20EURX-63T0FY0 | all | 2014.1.21 |
| | WD20EURX WD AV | WD20EURX-64HYZY0 | all | 2014.1.21 |
| | WD20EURX WD AV | WD20EURX-78T0FY0 | all | 2014.1.21 |
| | WD20EURS WD AV-GP | WD20EURS-63SPKY0 | all | 2012.11.6 |

Seznam kompatibilních HDD

9.3.2018

| | | | | |
|-----------------|--------------------------|--------------------|---------------------|---------------|
| 2T | WD20EVDS WD AV-GP | WD20EVDS-63T3B0 | all | |
| | WD20EURS WD AV-GP | WD20EURS-63Z9B1 | all | |
| | WD20EURS WD AV-GP | WD20EURS-63S48Y0 | all | |
| | WD20PURX WD AV | WD20PURZ-85GU6Y0 | all | 2014.4.7 |
| 1.5T | WD15EVDS WD AV-GP | WD15EVDS-63V9B0 | all | |
| | WD15EURS WD AV-GP | WD15EURS-63S48Y0 | all | |
| 1T | WD10EURX WD AV-GP | WD10EURX-63FH1Y0 | all | 2012.4.1 |
| | WD10EVCS WD AV-GP | WD10EVCS-63ZLB0 | all | |
| | WD10EVCS WD AV-GP | WD10EVCS-63E0B1 | all | |
| | WD10EVVS WD AV-GP | WD10EVVS-63E1B1 | all | |
| | WD10EVDS WD AV-GP | WD10EVDS-63N5B1 | all | |
| | WD10EVVS WD AV-GP | WD10EVVS-63M5B0 | all | |
| | WD10EURS WD AV-GP | WD10EURS-630AB1 | all | |
| | WD10PURX WD AV | WD10PURX-64D85Y0 | all | 2014.4.7 |
| 750G | WD7500AVCS WD AV-GP | WD7500AVCS-63ZLB0 | all | |
| | WD7500AVCS WD AV-GP | WD7500AVCS-63E0B1 | all | |
| | WD7500AVVS WD AV-GP | WD7500AVVS-63E1B1 | all | |
| 500G | | WD05PURZ-85U8XY0 | all | 2015.6.30 |
| | WD5000AUDX WD AV-GP | WD5000AUDX-63WNHY0 | all | 2012.4.1 |
| | WD5000YS WD Caviar RE2 | WD5000YS-01MPB0 | all | |
| | WD5000AVJS WD AV | WD5000AVJS-63YJA0 | all | |
| | WD5000AVVS WD AV-GP | WD5000AVVS-63ZWB0 | all | |
| | WD5000AVCS WD AV-GP | WD5000AVCS-63H1B1 | all | |
| | WD5000AVVS WD AV-GP | WD5000AVVS-63H0B1 | all | |
| | WD5000AVVS WD AV-GP | WD5000AVVS-63M8B0 | all | |
| | WD5000AVDS WD AV-GP | WD5000AVDS-63U7B0 | all | |
| | WD6400AVVS WD AV-GP | WD6400AVVS-63H0B1 | all | |
| | WD6400AVCS WD AV-GP | WD6400AVCS-63H1B1 | all | |
| 400G | WD4000YS WD Caviar RE2 | WD4000YS-01MPB0 | all | |
| | WD4000YR WD Caviar RE2 | WD4000YR-01PLB0 | all | |
| 320G | WD3200AVJS WD AV | WD3200AVJS-63WDA0 | all | |
| | WD3200AVJS WD AV | WD3200AVJS-63B6A0 | all | |
| | WD3200AVVS WD AV-GP | WD3200AVVS-63L2B0 | all | |
| 250G | WD2500YS WD Caviar SE16 | WD2500YS-01SHB0 | all | |
| | WD2500AVJS WD AV | WD2500AVJS-63WDA0 | all | |
| | WD2500AVJS WD AV | WD2500AVJS-63B6A0 | all | |
| | WD3200YS WD Caviar RE16 | WD3200YS-01PGB0 | all | |
| 160G | WD1600YS WD Caviar RE16 | WD1600YS-01SHB0 | all | |
| Hitachi | | | | |
| Capacity | HDD Series | HDD Model | DVR Firmware | Update |
| 500G | HITACHI CinemaStar 500GB | HCP725050GLA380 | all | |
| | HITACHI CinemaStar 500GB | HCS545050GLA380 | all | |
| SAMSUNG | | | | |
| Capacity | HDD Series | HDD Model | DVR Firmware | Update |
| 1.5T | HD154UI/CE | | all | |

| | | | |
|-----------------|------------------|------------------------|---------------|
| 1T | HA101UJ/CE | all | |
| | HD103SI/CEC | all | |
| 750G | HA751LJ | all | |
| 500G | HA500LJ/CE | all | |
| | HD502HI/CEC | all | |
| TOSHIBA | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 5T | MD04ABA500V | all | 2014.12.30 |
| 4T | MD04ABA400V | all | 2014.12.30 |
| | MD03ACA400V | all | 2014.8.18 |
| 3T | MD03ACA300V | all | 2014.8.18 |
| 3T | DT01ABA300V | all | 2013.8.23 |
| 2T | MD03ACA200V | all | 2014.8.18 |
| 2T | DT01ABA200V | all | 2013.8.23 |
| 1T | DT01ABA100V | all | 2013.8.23 |
| Hitachi | | | |
| Capacity | HDD Model | DVR Firmware | Update |
| 4T | HUS724040ALA640 | V3.0.1 Build 140310 | 2014.9.30 |